

City of Elkins Asbestos Inspection Report

Structure Located at:

418 Harpertown Road



City of Elkins

401 Davis Ave.

Elkins, WV 26241

Jessie Kittle

304-636-1414 ext. 1432

Summary of Inspection

Date of Inspection:	09/24/2025	License Number: Al011001
Inspector: Jessie Kittl	e	Building Address: 418 Harpertown Road
401 Davie	Ave.	
Elkins, WV	26241	
Reason for Survey:		
	Emergency Demolition:	
	Scheduled Demolition: X	
	Renovation:	
Type of Construction:	Frame X Masonry	Steel Beam Other
Floors:		Attic:
Basement:		Roof:
Crawlspace:		Pipe Tunnels:
Pipe Shafts:		Penthouse:
Sheds/Barns:	_1_	Age: <u>100</u>
Approximate Square I	Footage per Floor:	-
Approximate Total Sq	uare Footage: <u>1480</u>	-
Current Use: Vacant		
Past Use: Reidential		
Additions/Renovation	s: N/A	
Exterior:		
Metal Brick	WoodX Transite	Stone

Table of Contents

1.0 INTRODUCTION

- 1.1 Property Description
- 1.2 Purpose and Scope
- 1.3 Methods

2.0 ASBESTOS SURVEY

- 2.1 Visual Inspection
- 2.2 Analytical results

3.0 CONCLUSION

4.0 LIMITATIONS

5.0 SIGNATURE PAGE

APPENDICES

Appendix A Hot Sheet, Chain of Custody and Laboratory Results

Appendix B Photographs, Floor Plans

1.0 INTRODUCTION

1.1 Property Description

Address: 418 Harpertown Road Nature of Use: Vacant Residential

Number of Buildings: 2 Number of Floors: 2

Building Square Footage: 1480 Inspected By: Jessie Kittle Inspection Date: 09/24/2025

1.2 Purpose and Scope

The purpose of this asbestos inspection was to sample and analyze suspect Asbestos Containing Materials (ACM) which could present an exposure risk during potential demolition or renovation activities. The owner or operator of a demolition/renovation activity is required to thoroughly inspect the affected structure for the presence of asbestos, including Category I and Category II non-friable asbestos containing materials prior to the start of their project per the National Emissions Standards for Hazardous Air Pollutants (NESHAP 40 CFR, Part 61, Subpart M). The West Virginia Department of Environmental Protection is charged with enforcement of the NESHAP standards within the state. The suspect materials sampled during the inspection were limited to accessible areas within the interior and exterior of the building.

1.3 Methods

Suspected asbestos containing materials were identified for bulk sampling. These samples were randomly collected and placed into individual, sealable bags and labeled with unique identification numbers in accordance with sampling protocols set forth in 40 CFR Part 736. The samples were then analyzed by an independent third-party laboratory using Polarized Light Microscopy (PLM). Suspect materials were determined to be asbestos containing materials if they contained more than one percent asbestos as determined using PLM.

Under the Asbestos NESHAP, non-friable ACM is further divided into two categories: Category I and Category II. Category I non-friable ACM is asbestos containing packing, gaskets, resilient floor coverings, and asphalt roofing products containing more than one percent asbestos. Category II non-friable ACM is any material that is not Category I, containing greater than one percent asbestos that when dry, cannot be crumbled, pulverized, or reduced to powder by hand pressure. Category II non-friable ACMs, such as cement siding, transite board shingles, may become friable and release fivers if the sources are exposed to actions such as abrasion, drilling, cutting, fracturing, or hammering. During renovation/demolition activities, non-friable sources may become friable and thus may pose an exposure risk.

Based on the United States Environmental Protection Agency's definition, a material which contains greater than one percent asbestos, as determined using methods specified in Appendix E, Subpart E, 40 CFR Part 763, Section 1, Polarized Ligh Microscopy, is considered and ACM and must be handled according to OSHA, USEPA, and West Virginia Regulations.

2.1 Visual Inspection

Jessie Kittle performed an asbestos inspection on the structure located at 418 Harpertown Rd., Elkins, WV 26241. Jessie collected a total of one sample of suspected asbestos containing materials throughout the accessory structure for the purpose of testing by PLM for complete demolition of the structure. The main structure had extensive fire damage and was deemed unsafe for entry.

No destructive or extraordinary means were utilized to inspect or sample within walls or other structural components or within equipment. Sampling tools (prybar, hammer, utility knife, etc.) may have been used to collect bulk samples to obtain a sample representative of all layers of the suspect material. Consequently, the inspection and survey in this report was based on access to readily available areas within the structure: therefore, some areas containing ACM may not have been identified due to inaccessibility.

Suspected ACM materials observed at the time of the inspection were sampled and analyzed for asbestos content. The survey also established whether any of the material sampled could be considered friable and/or significantly damaged or capable of immediate worker exposure.

2.2 Analytical Results

A total of one bulk sample of suspected ACM was collected for analysis on 09/24/2025. The samples were assigned individual sample numbers, sealed in individual plastic bags, and transported with proper chain-of-custody documentation to Eurofins CEI, 730 SE Maynard Road, Cary, NC 27511 for analysis of the bulk samples. Refer to Appendix A for analytical data.

3.0 Conclusion

Damaged asbestos containing material may release asbestos fibers when disturbed by sawing, scraping, sanding, grinding, cutting, or abrading during demolition/renovation projects that would render the material friable. The EPA recommends that all ACM be removed by a certified asbestos contractor prior to any renovation/demolition projects that may impact the material and is required when the structure is being demolished. Removal is complex and must only be performed by a certified licensed asbestos contractor with special training and disposed of accordingly. Improper removal and disposal may increase health risks to workers, occupants, or the public.

The following tested positive for the presence of asbestos and either categorized as Category I or Category II:

See Appendix A: No ACM was present in samples

Be advised that the potential does exist for additional suspect ACM to be exposed during demolition/renovation projects. Work should be stopped immediately, and such materials should be sampled and analyzed for asbestos content prior to any further activities that could impact those materials.

Notes: Samples 01 were analyzed to contain less than one percent asbestos.

4.0 Limitations

The square/linear footage included in this asbestos assessment are estimates only and should not be used for bidding purposes. These figures should be confirmed by any contractor prior to entering the bidding process and should in no way represent final numbers for bidding purposes. The contractor may make an appointment to visually inspect the structure by contacting Jessie Kittle in person at 401 Davis Ave., Elkins, WV 26241, by phone at 304-636-1414 ext. 1432, or by email at ikittle@cityofelkinswv.gov.

5.0 Signature Page

Jessie Kittle, employed by the City of Elkins, has performed an asbestos inspection on the structure located at 418 Harpertown Rd., Elkins, WV 26241 in general conformance with the scope and limitation of the protocol stated in sections prior to this one.

The findings of this inspection are attached in Appendices A-B in the following pages.

The City of Elkins,

Jessie Kittle

Jessie Kittle

Asbestos Inspector

WV License Number: Al011001





Appendix A

Chain of Custody, Laboratory Analysis

Special Instructions:

VIABLES

.ogy MOLD

Laboratory Analysis Instructions

ent Sample ID Number

Medical Device Analysis

MICROBIOLOGY LABORATORY

919) 481-1413 eceived By: Date/Time: 10/02/2025 14:58:35 Date/Time: 09/29/2025 12:11:09 Sample Condition: Acceptable

RUSH STANDARD PRIORITY STANDARD SAME DAY RUSH PRIORITY STANDARD RUSH PRIORITY STANDARD RUSH PRIORITY STANDARD PRIORITY STANDARD **TAT DEPENDENT ON SPEED OF MICROBIAL GROWTH DUST

ASTM E1792 approved wipe media only**

Surface = SU Air = A

Dust = D

Paint = P

VALID MATRIX CODES

LAB NOTES

Tape = T

CHEMISTRY LABORATORY
Dust

ASBESTOS LABORATORY
PLM / PCM / TEM / NYS

DTL

RUSH

	- 8	Built Environment Testing	RES Job #: 6
SUBMITTED BY	INVOICE TO	CONTACT INFORMATION	SERIES
Company: City Of Elkins	il	Contact: Jessie Kittle	-1 PLM Standard
Address: 401 Davis Ave	Address: 401 Davis Ave	Phone: (304) 636-1414	
		Fax	
Elkins, WV 26241-3899	Elkins, WV 26241-3899	Cell: (304) 704-2722	
Project Number and/or P.O. #: 4182025	Project Zip Code: 26241	Final Data Deliverable Email Address:	
Project Description/Location: 418 HARPERTOWN ROAD		jwagler@cityofelkinswv.com	

694786

Effective

Square/linear footage are estimates only. The contractor should verify them before the bidding process begins.

Asbestos containing materials must be removed prior to demolition. Friable materials can be easily pulverized and present a significant hazard. For full clarification, please contact the following offices: WV Department of Environmental Protections, Division of Air Quality at 304-926-0499 ext. 1239 or the WV Bureau for Public Health (Asbestos Compliance Program) at 301-558-6718.



October 09, 2025

Jessie Kittle City Of Elkins 401 Davis Ave Elkins, WV 26241-3899

CLIENT PROJECT: 418 HARPERTOWN ROAD

LAB CODE: 694786-1

Dear Jessie,

Enclosed are asbestos analysis results for PLM Bulk samples received at our laboratory on October 2, 2025. The samples were analyzed for asbestos using polarizing light microscopy (PLM) per the EPA 600/R-93/116: Method for the Determination of Asbestos in Bulk Building Materials and EPA 40 CFR Appendix E to Subpart E of Part 763: Interim Method of the Determination of Asbestos in Bulk Insulation Samples.

Sample results containing >1% asbestos are considered asbestos-containing materials (ACMs) per EPA regulatory requirements. The detection limit for the EPA 600 Method is <1% by calibrated visual estimate.

Thank you for your business and we look forward to continuing good relations.

Kind Regards,

Kamila Reichert, Laboratory Director

Kamila Reinst

NVLAP 101768-0

730 SE Maynard Rd • Cary, NC 27511 • (919) 481-1413



ASBESTOS ANALYTICAL REPORT By: Polarized Light Microscopy

Prepared for

City Of Elkins

CLIENT PROJECT: 418 HARPERTOWN ROAD

LAB CODE: 694786-1

TEST METHOD: EPA 600 / R93 / 116 and EPA 40 CFR Appendix E to

Subpart E of Part 763

REPORT DATE: 10/09/25

TOTAL SAMPLES ANALYZED: 1

SAMPLES >1% ASBESTOS: 0

TOTAL LAYERS ANALYZED:

730 SE Maynard Rd • Cary, NC 27511 • (919) 481-1413

Asbestos Report Summary By: Polarized Light Microscopy

Project: 418 HARPERTOWN ROAD Lab Code: 694786-1

Method: EPA 600 / R93 / 116 and EPA 40 CFR Appendix E to Subpart E of Part 763

Client ID	Lab ID	Layer	Sample Description	Asbestos %
01	3768989		Cream/red siding	None Detected



ASBESTOS BULK ANALYSIS

By: Polarized Light Microscopy

Client: City Of Elkins Lab Code: 694786-1

 401 Davis Ave
 Date Received:
 10/02/25

 Elkins, WV 26241-3899
 Date Analyzed:
 10/09/25

Date Reported: 10/09/25

Project: 418 HARPERTOWN ROAD

Method: ASBESTOS BULK PLM, EPA 600 METHOD

Client ID	Lab	Lab	NON-ASBESTOS COMPONENTS				ASBESTOS
Lab ID	Description	Attributes	Fibrous		Non-Fibrous		%
01 3768989	Siding	Heterogeneous Cream/red Fibrous Bound	50%	Cellulose	40% 10%	Tar Gravel	None Detected



LEGEND:

Non-Anth = Non-Asbestiform Anthophyllite Non-Trem = Non-Asbestiform Tremolite Calc Carb = Calcium Carbonate

METHOD: EPA 600 / R93 / 116 and EPA 40 CFR Appendix E to Subpart E of Part 763

REPORTING LIMIT: 1% by calibrated visual estimation

REGULATORY LIMIT: 1%

Due to the limitations of the EPA 600 / R93 / 116 method, nonfriable organically bound materials (NOBs) such as vinyl floor tiles can be difficult to analyze via polarized light microscopy (PLM). EPA recommends that all NOBs analyzed by PLM, and found not to contain asbestos, be further analyzed by Transmission Electron Microscopy (TEM). Please note that PLM analysis of dust and soil samples for asbestos is not covered under NVLAP accreditation. Estimated measurement of uncertainty is available on request.

Eurofins Built Environment Testing East, LLC makes no warranty representation regarding the accuracy of client submitted information in preparing and presenting analytical results. Interpretation of the analytical results is the sole responsibility of the client. This report relates only to the samples tested or analyzed and may not be reproduced, except in full, without written approval by Eurofins Built Environment Testing East, LLC. Samples were received in acceptable condition unless otherwise noted. This report may not be used by the client to claim product endorsement by NVLAP or any other agency of the U.S. Government.

Information provided by customer includes customer sample ID and sample description.

Samantha Taylor Analyst

DATA QA:

Samantha Webster 10/9/2025

Sanatlal

APPROVED BY:

Kamila Reichert, Laboratory Director

Kamila Reinst

730 SE Maynard Rd • Cary, NC 27511 • (919) 481-1413

Page 2 of 2

City Of Elkins Sample Notes

RES #:

Project Description/Location: Project Number and/or P.O. #:

694786 4182025

418 HARPERTOWN ROAD

Sample Note FAUX BRICK SIDING

Quantity

Sampler(s)

9

Client Sample ID

Page 1 of 1

City Of Elkins Sample Locations

RES #:

Project Description/Location: Project Number and/or P.O. #:

4182025

694786

418 HARPERTOWN ROAD

Sample Location
GARAGE SIDING

9


Client Sample ID

Page 1 of 1

Appendix B Photographs and Floor Plans







Additions

# Lowe	r First	Secon	d Third	Area	Value
0 Refe	to Base Area Desc	ription		740	\$0
1	Open frame porch			80	\$440
2	Open frame porch			288	\$1,590

Show dimensions Show addition numbers